



TOLEDO FIRE & RESCUE DEPARTMENT



Directive: 24-15 - Structural Stability Bracing and COT Buildings Dept. response

2024 Directives

Date Issued: 10/21/2024

Last Modified: 02/23/2026 15:00

[Export 24-15 to PDF](#)

[Export -All 2024 Directives- to PDF](#)

THIS HAS BEEN REPLACED BY DIRECTIVE 26-06 "TRT Shoring Placard and Responsibility Statement"

The following procedure shall be followed when the Toledo Fire and Rescue Department(TFRD) erects structural stability bracing (shoring) in or on a structure residing within the City of Toledo (COT) on an incident.

The Incident Commander shall request a member of the COT Department of Building Inspection through Fire Dispatch to respond to the scene. This practice will allow a second set of eyes to verify that proper shoring has taken place. Additionally, the building owner will be issued 30-day orders which will drive compliance and assist TFRD in retrieving the shoring equipment that was utilized. This will also prompt the owner to make the necessary repairs due to an unsafe structure. The COT Department of Building Inspection can also help verify if the building needs to be vacated until permanent repairs are complete.

Effective Date: October 21, 2024

Permanent link:

https://www.tfrdweb.com/dokuwiki/doku.php?id=2024_directives:24_15

Last update: **02/23/2026 15:00**

